Industrial Pressure Monitoring

Ensure safety of pressure vessels in processing plants.

Monitor gas raw materials in industrial manufacturing.

Know that fire extinguishing cylinders are charged and ready in the event of a fire.

Monitor the temperature of pressure vessels, ensuring they are within limits.

Use the ORB-X1 current source or voltage input to measure pressure from a 4-20mA or voltage output pressure sensor.

Connect a pressure switch directly to an ORB-X1 input.

Use K, J, T, N, S, E, B and R-Type thermocouples connected directly to the ORB-X1.

Configure warnings on the Senquip Portal to receive online, SMS and email warnings and alarms.

SENQUIP

SENSOR CONNECTIVITY MADE EASY